	Parport	START		1st Step		2nd Step		3rd Step	
Signal	pin#	Volts	Hal Show	Volts	Hal Show	Volts	Hal Show	Volts	Hal Show
В	5	0	OFF	0	OFF	5	ON	5	ON
Bnot	6	5	OFF	5	OFF	0	ON	0	ON
Α	7	0	OFF	5	ON	5	ON	0	OFF
Anot	8	5	OFF	0	ON	0	ON	5	OFF