

RAZOR CUT 45/80 CNC 14 PIN SOCKET PINOUTS

PIN

3	START
4	START
5	VDIV-
6	VDIV+
12	TRANSFER
13	GND
14	TRANSFER