Probe A to TxA
Probe A GND to TxB

Probe B Not conneted

Probe A to RxA to Data-

Probe B to RxB to Data+

Scope set to A-B

Probe GNds not connected

Linxcnc off

Probe A to RxA to Data-

Probe B to RxB to Data+

Scope set to A-B

Probe GNds not connected

<u>Linxcnc ON</u>