

CombiMill Gearbox

	A	B	C	D	E	F	G	H	I
1	S – Range	Motor High speed	GearShift	Gear A	Gear B	Gear C	Gear D	Gear E	
2			Hi or Lo						
3		Mesa output 10	Mesa Input 14	Mesa Input 09	Mesa Input 10	Mesa Input 11	Mesa Input 12	Mesa Input 13	
4									
5	2001 – 2500	HighSpeed	Hi selected	Selected					AH1 = input 09 + input 14 + output 10
6									
7	1501 – 2000	HighSpeed		Selected					AH2 = input 09 + output 10
8									
9	1191 – 1500	HighSpeed	Hi selected		Selected				BH1 = input 10 + input 14 + output 10
10									
11	1001 – 1190	HighSpeed			Selected				BH2 = input 10 + output 10
12									
13	751 – 1000			Selected					GearAL = input 09
14									
15	596 – 750		Hi selected		Selected				GearBH = input 10 + input 14
16									
17	451 – 595				Selected				GearBL = input 10
18									
19	361 – 450		Hi selected			Selected			GearCH = input 11 + input 14
20									
21	271 – 360					Selected			GearCL = input 11
22									
23	216 – 270		Hi selected				Selected		GearDH = input 12 + input 14
24									
25	161 – 215						Selected		GearDL = input 12
26									
27	126 – 160		Hi selected					Selected	GearEH = input 13 + input 14
28									
29	80 – 125							Selected	GearEL = input 13