

12A8 Brush Type PWM Servo Amplifier

- 1 +5V 3mA Out
- 2 Signal GND
- 3 -5V 3mA Out
- 4 +REF IN
- 5 -REF IN
- 6 -Tach IN
- 7 +Tach / GND
- 8 Current Monitor
- 9 Curr Ref Out
- 10 Cont Current Limit
- 11 INHIBIT IN
- 12 +INHIBIT IN
- 13 -INHIBIT IN
- 14 FAULT OUT
- 15 NC
- 16 NC

CA-LC5-W4-NC
(Digital)

- TB5
- DRV
- 1 ENAO-
- 2 ENAO+
- 3 GND
- 4 AOUTO

TB3 Encoder

