



Hypertherm PowerMax 125 RS485 Connection Reference



Connection at Machine Diagram



USB to RS485 Converter: XC4136



RS232 PCI Card using same connector as the above USB/RS485 Converter

Sunix P/N: SER5037A

