


If I try to load a TAP file is get this error.



Not sure if the problem is the LinuxCNC or the 2 different CAM software programs. I did not see these types of problems when I used other controller software. I'm sure things will get sorted out soon. I had start up problems with QTPlasmaC but with help it is working great now.