




# CNC Stepper Motor Driver 6 Axis Interface Board adapter

with Optical isolation, protect your PC

## Product Description

### Product Description





## ***Features :***

**CNC Stepper Motor Driver 6 Axis Interface Board adapter**

**It can connection 6 drivers and control 6 motors in the same time;**

**Built in DB25 male connector.**

**DB25 Output Pin:P1,P2,P3,P4,P5,P6,P7,P8,P9,P14,P16,P17.**

**DB25 Input Pin: P10,P11,P12,P13,P15.**

**DB25 GND Pin: P18-P25.**

**Power voltage is 5VDC and support with MACH3 etc. software**

**Built in Optical-coupler.**

**you can set these pins according to software as follows:**

**Output pin: P1,P2,P3,P4,P5,P6,P7,P8,P9,P14,P16,P17.**

**P2 – X axis Pulse, P3 – X axis Direction;**

**P4 – Y axis Pulse, P5 - Y axis Direction;**

**P6 – Z axis Pulse, P7 – Z axis Direction;**

**P8 - A axis Pulse, P9 - A axis Direction;**

**P14 - B axis Pulse, P1- B axis Direction;**

**P16 - C axis Pulse, P17- C axis Direction**

**Input pin: P10 ,P11, P12, P13, P15**

**Set them for Emergency Stop and X Y Z Limit switch**

**Changzhou Wantai Electrical Appliance Co., Ltd**

<http://www.wantmotor.com>

Contact: Saron Shen

E-mail: [mike@wantmotor.com](mailto:mike@wantmotor.com)

TEL: 0086-519-85138377

FAX: 0086-519-85139178

Mobile: 0086-13401312691

MSN: [saron1@live.cn](mailto:saron1@live.cn)

Skype: happy\_saron