


1.3 Control port CN1 and Motor encoder port CN2 Connection diagram



Special Note:

If the pulse command signal is a 24V power supply, the resistor must be concatenated at puls-, sign-2K, 5%, 0.25W, otherwise it may damage the pulse command port.