



I recommend replacing the transistor with a pin compatible mosfet rated for at least 24v like a 2N7002P

Vers TS v2.4

Sheet: /  
File: Probe.sch

**Title:**

Size: A4  
KiCad E.D.A. kicad 5.1.5

Date:

**Rev:**  
Id: 1/1